

+01900043 09/900,043

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,800,539 B2
DATED : October 5, 2004
INVENTOR(S) : Takahiro Yajima et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6.

Line 27, "Mark ▼" should read -- Mark ▲ --.

Column 7.

Line 42, "Mark ▼" should read -- Mark ▲ --.

Column 8.


Lines 55 and 59, "(Mark ▼" should read -- (Mark ▲ --.

Column 10.

Line 38, "1000 sccm." should read -- 10000 sccm. --.

Signed and Sealed this

Nineteenth Day of April, 2005



JON W. DUDAS
Director of the United States Patents and Trademark Office